

Porcas - SAM_14

Porcas DIN 934

	Passo	Chave	Espessura	Ang °	(Ref)
M3	0,50	5,0	2,4	30	4,9
M4	0,70	7,0	3,2	30	6,9
M5	0,80	8,0	4,0	30	7,9
M6	1,00	10,0	5,0	30	9,8
M8	1,25	13,0	6,5	30	12,7
M10	1,50	17,0	8,0	30	16,7
M12	1,75	19,0	10,0	30	18,5
M14	2,00	22,0	11,0	30	21,6
M16	2,00	24,0	13,0	30	23,4
M20	2,50	30,0	16,0	30	29,2
M24	3,00	36,0	19,0	30	35,1
M30	3,00	46,0	24,0	30	44,5
M36	4,00	55,0	29,0	30	53,5
M42	4,50	65,0	34,0	30	63,5

